Weldon setup overview

Absolute connection — Optional connection




1/2UNF-MC2
1/2UNF-MC3
Drill chuck connection
IBK.15
Adapter spindle
Arbor MT2
auto lubricant
IMC.20
▶ Arbor MT2
quick exchange
IMC.2Q
Arbor MT2
Arbor MT3
auto lubricant
IMC.30/19-N
▶ Arbor MT3
quick exchange
IMC.3Q
Arbor MT3
B16-MC2
B16-MC3
Drill chuck connection
Connection 19.05 mm Weldon
Adapter 19.05 mm Weldon
to 1/2"x 20 UNF
IBK.14
Adapter 19.05 mm
Weldon to B16
IBK.16-14
1/2"x 20 UNF
IBK.13
1/2"x 20 UNF
quick connect
IBK.13Q
1/2"x 20 UNF Quick
connect with lock
IBQ.13
Drill chuck
1/2"x 20 UNF
B16
IBK.13-B16
B16
IBK.16
B16 quick connect
IBQ.16
Drill chuck
B16
Twist drills
• DIA Ø 1 - 13 mm
Step drills
• DIA Ø 4 - 12 mm
• DIA Ø 4 - 20 mm
• DIA Ø 6 - 30 mm
Tapping
• With drill chuck up to 6 mm